

JUNE 2011

Plastic Backed Mirror Glass

Also Known as: Replacement Mirror Glass, Outside Mirror Glass, Mirror Glass Assembly



View Video at DormanProducts.com

36 NEW SKUs!

Reduce Repair Cost

Replace Just the Failed Part



STORE STOCK



Front View



Rear View

56633 [R]

56632 [L]

Jetta

2007-99

(Electric, Heated, Clear Glass)

Pop Code: B

VIO: 904,047



Includes Backing Plate for Snap-In Replacement

Radiator Fan Relay

Controls Fan speeds



902-209
Crown Victoria,
Grand Marquis,
Town Car
2011-06

Pop Code: C
VIO: 864,942

FAILURE MODE:

- Electrical failure and corroded Harness Connectors
- Results in Fan malfunction causing the engine to overheat

Integrated Door Latch Actuators

Electric Motor located inside the door used to lock or unlock a vehicles' Door Locks

7 NEW SKUs!

931-400 [FL]
4Runner, Camry,
Corolla, Sienna, Solara
2010-02

Pop Code: D
VIO: 5,834,791



FAILURE MODE:

- Electrical burnout
- Results in inoperative power door locks

ABS Tone Ring

Also Known as
ABS Tone Wheels

Not available in the aftermarket as a component (only as part of the CV Shaft Assembly)



Reduce Repair Cost
No need to
Replace CV Shaft

917-533

Lancer

2007-02

Pop Code: D

VIO: 370,776

FAILURE MODE:

- Cracks over time due to fatigue and corrosion

LINE UPDATES

Sway Bar Kit

Replacement for
RUST Prone Parts



927-105
Avalanche, Escalade,
Suburban, Tahoe, Yukon
2006-00

Pop Code: D
VIO: 2,705,982

Original Tubular Design

Corrosion Leads to Ends Splitting and Eventually Breaking

DORMAN
Engineered

Solid Forged Design Eliminates Possibility of Ends Breaking

Timing Belt Adjuster

Also Known as
Timing Belt
Tensioners

Great "add-on" sale to Timing Belts and Timing Belt Kits



420-180
300, Concorde,
Intrepid
2002-93

Pop Code: D
VIO: 813,532

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492