

JULY 2011

Radiator Fan Relay Kit

Controls Fan speeds



STORE STOCK



Wire Harness Included for a Complete Repair

902-310

Caravan, Liberty, Pacifica, Town & Country, Voyager, Wrangler 2008-02

Pop Code: B
VIO: 2,221,163

FAILURE MODE:

- Electrical failure and corroded Harness Connectors
- Results in Fan malfunction

Wheel Center Caps

Covers Lug Nuts at the center of the wheel

18 NEW SKUs!

909-002

Avalanche, Sierra, Silverado, Suburban, Tahoe, Yukon 2007-99

Pop Code: C
VIO: 8,052,066



FAILURE MODE:

- Falls off during regular use
- Breaks during service

Battery Vent Tubes

Provides ventilation for the battery located inside the body of the vehicle

Replace when servicing battery



924-252

Aurora, Bonneville, Deville DTS, LeSabre 2007-99

Pop Code: C
VIO: 1,540,888

ALSO AVAILABLE!

924-253
Cobalt 2008-05, G5 2008-07, HHR 2008-06
Pop Code: C
VIO: 1,032,404

924-254
BMW 2010-82
Pop Code: D
VIO: 2,987,226

FAILURE MODE:

- Warm climates degrade the Battery Vent Tubes causing them to become hard and brittle
- Often cracks when battery is serviced

Cup Holder Inserts

Replaces worn or missing cup holders.



STORE STOCK

41000 [Front of Shifter]
41001 [Rear of Shifter]

Ascender, Bravada, Envoy, Rainier, Trailblazer 2009-02

Pop Code: B
VIO: 1,980,802

Exhaust Manifold Hardware Kits

Attaches Manifold to Cylinder Head

3 NEW SKUs!



674-000

Ford 4.6, 5.4, 6.8L 2011-97

Pop Code: C
VIO: 13,348,637

Replace when servicing Exhaust Manifold

FAILURE MODE:

- Corrosion, breakage

Door Panel Install Kits

Door Clips are often lost or broken when removing the panel to service the Window Regulator



Includes All Hardware Needed to Complete the Repair

Add-on sale to Window Regulators



STORE STOCK

702-007

Accord 1997-86, Civic 2000-92, CL 1997

Pop Code: B
VIO: 6,019,669

JULY 2011


LINE UPDATES

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET

NOW OFFERING
1481
TOTAL SKUs

31 NEW SKUs!



STORE STOCK

748-228 [RL]
748-229 [RR]
Escalade, Tahoe, Yukon
2006-00
Window Regulator with Motor
Pop Code: B
VIO: 2,934,770



749-556
Expedition, Navigator
2002-97
Window Regulator
w/o Motor
Pop Code: C
VIO: 1,012,075

748-582 [FL]
748-583 [FR]
Galant 2009-04
Window Regulator with Motor
Pop Code: D
VIO: 299,610



Visit www.DormanProducts.com/GetMore
for Product Information, Installation Sheets, Product Videos and More!
[Scan here to learn more](#)



Ignition Lock Housing

Also Known as Lock Cylinder Case

Reduce Repair Cost:
Replace Just the Failed Part




924-708
Achieva, Cavalier,
Grand Am, Skylark, Sunfire
1999-97

Pop Code: D
VIO: 1,023,075

FAILURE MODE:

• Passlock Sensor fails resulting in no start or "security" light



Ignition Lock Assembly

Wiper Transmission



602-301
Escape 2006-01,
Mariner 2006-05
Pop Code: D
VIO: 825,635

Air Intake Hose



696-711
Corolla 2008-05
Pop Code: D
VIO: 1,082,272

BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492