

AUGUST 2011

## Fuel Pump Driver Module

Controls voltage to Fuel Pump in order to maintain proper fuel pressure over the full operating range of the engine.



**STORE STOCK!**

**590-001**  
Ford F150,  
2008-04  
Explorer Spt. Trac.,  
2010-07

**Pop Code: A**  
**VIO: 2,122,008**



**Original Aluminum Housing –  
Extremely failure prone  
due to corrosion**

- **Powder coated** to prevent corrosion
- **Mounting Screws Improved** with rubber bushings to position steel away from mounting surface.
- **Improved micro-processor** provides greater response time and reliability by protecting the Fuel Pump and the module itself from opens and electrical shorts.

## Radiator Fan Relay Kit

Controls Fan speed



**Wire Harness Included for  
a Complete Repair**

**902-706**  
Mini Cooper  
2008-03

**Pop Code: D**  
**VIO: 172,848**

**FAILURE MODE:**

- Electrical failure and corroded Harness Connectors
- Results in Fan malfunction

## Driveshaft Support Bearings

Also Known as Center Support Bearing  
Supports the Driveshaft at center point



**934-404**  
Highlander, RX  
2010-01

**Pop Code: D**  
**VIO: 1,399,705**

**FAILURE MODE:**

- Rubber Isolator deteriorates resulting in Drivetrain vibration or clunking sound

## Water Separator Valve

**DIESEL**

Lever allows water to be drained from the Fuel Filter Housing



**904-221**  
Ford 7.3L Diesel  
1997-94

**Pop Code: C**  
**VIO: 323,411**



**FAILURE MODE:**

- O-Rings break down from fuel exposure

## Window Channels

Attaches Window Glass to Regulator Assembly. Actuates with the Regulator to raise and lower Window Glass



**Plastic Brackets Upgraded to  
Metal for Improved Durability**



**924-248**  
Montana, Silhouette, Terraza,  
Transport, Uplander, Venture  
2008-97

**Pop Code: C**  
**VIO: 2,543,944**

**FAILURE MODE:**

- Plastic Brackets snap causing the glass to become loose or break from the Window Regulator

BE THE FIRST TO KNOW!  
Sign Up at [www.DormanProducts.com/Signup](http://www.DormanProducts.com/Signup)

Customer Service:  
**1-800-523-2492**

AUGUST 2011

**Ignition Lock Housing** — Also Known as Ignition Lock Cylinder Case

Mounts to Steering Column and contains the Passlock Sensor



**924-713**  
GM Vehicles  
2009-00  
**Pop Code: C**  
VIO: 11,432,218

**ALSO AVAILABLE**

**924-714**  
Express, Savana  
2007-03

**Pop Code: C**  
VIO: 575,771

**FAILURE MODE:**

- Passlock Sensor failure causes a 'no start' condition accompanied by a flashing security light

**Door Panel Install Kit**

Door Clips are often lost or broken when removing the panel to service the Window Regulator

**STORE STOCK!**



**COMPLETE KIT**

Includes all hardware needed to complete the repair

Add-on sale to Window Regulators

**702-006**  
Alero, Grand AM  
2004-99

**Pop Code: A**  
VIO: 3,114,406

**Sliding Door Harness**

Delivers power to Power Sliding Door Motor



**747-310 (L)**  
**747-311 (R)**  
Caravan, Grand Caravan,  
Town & Country  
2009-04

**Pop Code: D**  
VIO: 1,223,165

**FAILURE MODE:**

- Wires inside the Harness Channel kink from repeated flexing over years of use  
Failure results in the Power Sliding Door Motor becoming inoperable

LINE EXTENSIONS

**Tail Lamp Circuit Board**



**923-207**  
Caravan, Town & Country  
2007-01

**Pop Code: C**  
VIO: 2,176,276

**ALSO AVAILABLE**

**923-206**  
F Series Pickup 2008-99,  
Ranger 2003-95

**Pop Code: D**  
VIO: 4,119,157

**Exhaust Manifold Kits**



**STORE STOCK!**

**674-811**  
Camry, Solara  
2006-02

**Pop Code: B**  
VIO: 1,395,453

