

FEBRUARY 2012

Natural Vacuum Leak Detection (NVLD) Pump

Monitors for fuel system vapor leakage

STORE STOCK



Failure Sets "Check Engine" Light



310-500
Chrysler
2009-03
Jeep
2006-04
Pop Code: BN
VIO: 4,046,498

FAILURE MODE:

- Fails due to dirt and debris entering the part or from inactivity due to long periods between test cycles
- Failure sets the Check Engine light and will signal a false leak in the system

Hub Lock Actuator

Latch tabs lock into place actuating the Hub Assembly and enabling 4WD

Reduce Repair Cost—
Replace just the failed part
instead of the entire Hub Assembly



917-502
Excursion, Expedition,
F Series Pickup,
Navigator
2005-01

Pop Code: C
VIO: 1,359,560

FAILURE MODE:

- Tabs in the assembly wear causing an inability to engage the 4WD Hub Assembly

Oil Cooler Adapter Seal

Seals the Engine Oil Cooler to Adapter on Engine Block



917-036
Nissan 2.5, 3.5, 4.5, 5.6L
2011-02

Pop Code: C
VIO: 2,368,747

FAILURE MODE:

- Seals dry out causing oil leakage

LINE EXTENSIONS

Tailgate Cables

38502
F Series Pickup
2010-04
Mark LT
2008-06 Styleside Bed

Pop Code: A
VIO: 2,607,064



STORE STOCK

ALSO AVAILABLE!

38560
Suburban
1991-99
20" Long
Pop Code: D
VIO: 77,300

FAILURE MODE:

- General wear and tear

ABS Tone Wheel

Not available in the aftermarket as a component –
only as part of the CV Shaft Assembly



Reduce Repair Cost—
Need to Replace CV



917-530
Explorer, Mountaineer
2010-07

Pop Code: C
VIO: 1,288,712

FAILURE MODE:

- Cracks over time due to fatigue and corrosion
- Results in the ABS Sensor misreading the Tone Wheel, causing an ABS failure code and ABS pulsing continuously

FEBRUARY 2012

Body Mount Kit

924-014
Crown Victoria, Grand Marquis, Marauder, Town Car 2010-03

Pop Code: C
VIO: 1,005,609



FAILURE MODE:

- Mounts compress, crack, and separate
- Failure results in clunking sound and reduced ride control

Remanufactured Transfer Case Control Module

Plug & Play for Easy Installation (No Programming Required)



599-108
C/K Pickup, Escalade, Suburban, Tahoe, Yukon 2000-97

Pop Code: D
VIO: 1,252,236

ALSO AVAILABLE!

599-106
Bravada, S10 2002-98
Sonoma 2002-98
Pop Code: W
VIO: 1,861,061

599-107
Astro, Safari 2005-99
Pop Code: W
VIO: 399,949

FAILURE MODE:

- Corrosion over time
- Failure results in the inability to shift in and out of 4WD

Wheel Hub

930-012
Forenza 2008-04
Reno 2008-05

Pop Code: C
VIO: 327,992



FAILURE MODE:

- Bearing seizes itself to the Hub, preventing re-use

Exhaust Manifold Hardware Kits

3 NEW SKUs!



03407B
Ford 4.2, 5.0, 5.8L 1997-80

Pop Code: C
VIO: 3,633,342

Fits Dorman Manifolds:
674-152, 674-153, 674-169

Hood Release Cable



912-043
Mustang 2004-94


Pop Code: D
VIO: 1,240,085

FAILURE MODE:

- Cable breaks over time

Leaf Spring

Replacement for Rust **RUST** Prone Parts



929-105 [R]
CBravada 1994-91
S10 1994-83

Pop Code: D
VIO: 402,935

FAILURE MODE:

- Fatigue, crack, and rust over time
- Failure results in total failure of the part or lost spring tension, causing the part to sag

FEBRUARY 2012

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET



748-978 [RL]
748-979 [RR]
Altima
2006-02
Power Window Regulator
w/ Motor

Pop Code: C
VIO: 1,093,543

NOW OFFERING
1545
TOTAL SKUs

25 NEW SKUs!

748-982 [RR]
748-983 [RL]
Malibu
2011-08

Pop Code: C
VIO: 420,346



Visit www.DormanProducts.com/GetMore
for Product Information, Installation Sheets, Product Videos and More!

Scan here to learn more ▶

