

DORMAN[®]
NEW SINCE 1918

www.DormanProducts.com

FORMERLY "DEALER ONLY" PARTS

Now Available to the Aftermarket

DECEMBER 2010

Remanufactured Instrument Clusters

599-322
Express Van, w/o
Tachometer,
Gas Engine
2005-03
Pop Code: SO
VIO: 573,787



Ready to Install – Fully Programmed
with Mileage & VIN

FAILURE MODE:

- Erratic or non-functional Gauges
- Inaccurate readings

ALSO NEW

599-317
Cavalier w/ Tachometer
2005-00
Pop Code: SO
VIO: 884,414

599-318
Sunfire w/ Tachometer
2005-03
Pop Code: SO
VIO: 100,893

599-324
Impala, Monte Carlo
w/ Tachometer, 4 Gauge
2005-01
Pop Code: SO
VIO: 1,361,507

Spindle Stub Shafts

Connects the Wheel Bearing to Rear Suspension of the Vehicle

**STORE
STOCK**

905-300
Focus
2008-00
Pop Code: B
VIO: 6,892,116



FAILURE MODE:

- Rear Wheel Bearing can seize onto the Spindle Stub Shaft causing shaft to fail

Brake Backing Plates (Brake Dust Shields)

Protects the Brake Mechanism from Road Debris.

**STORE
STOCK**

924-212
Ford Full Size Trucks
2004-99

Pop Code: B
VIO: 6,840,192



FAILURE MODE:

- Rust and corrosion

Remanufactured Transfer Case Control Modules

Plug & Play for Easy Installation (No Programming Required)

Fully Remanufactured &
Tested for Quality Assurance

599-100
Bravada, S10,
Sonoma, 4WD;
Electronic Shift(NP1)
2005-98

Pop Code: CN
VIO: 2,137,314



ALSO NEW

599-101
S10, SONOMA, 4WD
1997-94

Pop Code: CN
VIO: 574,374

FAILURE MODE:

- Corrosion, components degrade over time
- Will not shift in and out of 4WD

View Installation Video
at DormanProducts.com



BE THE FIRST TO KNOW!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

DECEMBER 2010

Transfer Case Motor Encoder Ring

Indicates Transfer Case Motor position to 4WD Control Module Motor



600-120
GM Full Size Trucks,
w/Push Button Control
Transfer Case
2007-03

Pop Code: DN
VIO: 4,651,468

FAILURE MODE:

- Fails due to wear or water intrusion
- Results in the inability to shift in and out of 4WD, sets check engine light

Vent Window Motors

Controls Pivoting Rear Windows on Minivans and Sport Utility Vehicles.



948-300 L
948-301 R
Chrysler Minivans
2009-01

Pop Code: CN
VIO: 2,454,934

ALSO NEW

948-302 L **948-200 L**
948-303 R **948-201 R**
Chrysler Minivans Freestar, Monterey,
2000-96 Windstar 2007-96

Pop Code: DN
VIO: 1,877,559

Pop Code: DN
VIO: 1,326,679

FAILURE MODE:

- Motor burnout, electrical failure or water intrusion
- Window becomes stuck in one position

LINE UPDATES

Wheel Hubs

8 NEW SKUs!



930-250
3 Series,
w/Disc Brakes
2006-92
Pop Code: CN
VIO: 1,271,078

FAILURE MODE:

- Bearing Race seizes itself to the Hub preventing re-use

Heater Hose Assembly

Connects the Thermostat Heater Core to the Radiator Hose



626-209
Sable, Taurus
2000-96

Pop Code: CN
VIO: 719,902

FAILURE MODE:

- Plastic dries out over time
- Results in cracking and coolant leak

Wiper Transmissions

602-208
Ion
2007-03

Pop Code: CN
VIO: 454,930




FAILURE MODE:

- Fails due to regular use or damage from clearing heavy snow and ice

Window Regulators

25 NEW SKUs!



749-544 RL
749-545 RR
Ford Full Size Trucks
2010-07

Pop Code: DN
VIO: 162,272

Air (Blend) Door Actuators

Electric Motor that Controls the Opening and Closing of the Air (Blend) Door



604-113
GM Full Size Trucks
2002-99

Pop Code: DN
VIO: 3,485,152

FAILURE MODE:

- Fails due to motor burnout or electrical failure
- Causes improper function of the A/C, heat, and/or defrost

AC Bypass Pulleys



34237
Cherokee,
Dakota, Wrangler
2002-96

Pop Code: DN
VIO: 955,223

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492

DORMAN[®]
NEW SINCE 1918

www.DormanProducts.com

FORMERLY "DEALER ONLY" PARTS

Now Available to the Aftermarket

DECEMBER 2010

LINE UPDATES (Continued)

Air Bag Clock Springs

525-016
GM Full Size Trucks
2007-03
Pop Code: DN
VIO: 7,951,808



FAILURE MODE:

- Fails due to wires breaking or separating from contacts
- Failure causes the vehicle's Air Bag warning light to illuminate

Harmonic Balancers

3 NEW SKUs!



594-220
Bravada, Envoy,
Rainier, Trailblazer
2009-02

Pop Code: DN
VIO: 1,789,262

FAILURE MODE:

- Rubber deteriorates due to heat
- Failure can cause engine damage

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492