

JANUARY 2012

Transmission Oil Coolers

Air flows through the fins of the Transmission Oil Cooler to cool the transmission oil flowing through it



REPLACEMENTS

No Need to Hassle
 with Universal SKUs

FAILURE MODE:

- Corrosion due to exposure to the elements
- Damaged by being hit or becoming clogged by road debris
- Damaged in a crash
- Clogs over time
- Replace with Transmission

918-202
 F Series Pickup
 2008-04
 Mark LT
 2008-06

Pop Code: C
VIO: 1,984,026



ALSO AVAILABLE!

918-211
 E Series Van
 2010-08
Pop Code: D
VIO: 180,772

Oil Separator Cover

Cover located on the back of the Engine Block that separates oil drawn through the PCV system from the Intake Vacuum

Constructed of metal to eliminate
 warping of original plastic design

FAILURE MODE:

- Original plastic piece warps over time due to heat exposure
- Failure results in oil leakage



917-034
 Forester, Impreza
 2011-06
 Legacy
 2009-07

Pop Code: D
VIO: 501-849

LINE EXTENSIONS

Remanufactured Climate Control Module

Plug & Play for Easy Installation (No Programming Required)

Remanufactured and Tested for Quality Assurance

- 100% replacement of backlight bulbs



599-004
 Envoy 2008,
 Trailblazer 2009

Pop Code: C
VIO: 44,360

FAILURE MODE:

- Mode selection failure
- Bulb blowout
- Wear and tear

Door Latch Actuator

Electric motor located inside the door used to lock or unlock a vehicle's door locks

931-001 [FL]
931-002 [FR]
 Grand Cherokee
 2003-99

Pop Code: C
VIO: 936,011



FAILURE MODE:

- Electrical burnout

JANUARY 2012

PCV Elbow Kit



46027
 Sable, Taurus
 2003-00
 Pop Code: C
 VIO: 419,795

Remanufactured Instrument Clusters

Ready to Install – Fully Programmed with Mileage and VIN



599-329
 Century, Regal
 1998-97
 Pop Code: SO
 VIO: 227,147

No vehicle downtime. Special order ships same day.

ALSO AVAILABLE!

FAILURE MODE:
 • Electrical burnout

*US Only

599-633
 Mustang 2005
 Pop Code: SO
 VIO: 131,969

Trailing Arm Bushing

905-303 [RL]
 Focus
 2007-00
 Pop Code: C
 VIO: 1,546,848



Brake Proportioning Valve



905-955
 Cavalier, Sunfire
 2005-00
 Pop Code: D
 VIO: 1,338,494

FAILURE MODE:

- Corrosion
- When servicing the brake line, fittings can seize inside valve and threads can pull out of aluminum body

Air Intake Hose

Brings air from the Air Flow Meter into the Throttle Body and keeps dirt and debris from entering the Engine



696-400
 Sephia
 2001-98
 Spectra
 2004-00
 Pop Code: D
 VIO: 296,131

FAILURE MODE:

- Fails due to the hose cracking from age and vibration
- Failure allows air to bypass the Air Flow Meter causing the Engine to stumble and stall

Hinge Pin & Bushing Kit



Replace just the failed Pin and Bushings instead of the entire Door Hinge



COMPLETE KIT

Kit includes Hinge, Bushings, Clips, Nuts, Shims and Pins

38481

Dakota 2004-99,
 Durango 2009-04

Pop Code: D
 VIO: 1,116,375

FAILURE MODE:

- Wear and tear

Leaf Spring

Replacement for **RUST** Prone Parts

929-205 [R]
 F Series Pickup
 1997-90

Pop Code: D
 VIO: 2,194,712



FAILURE MODE:

- Fatigue, crack and rust over time
- Failure results in total failure of the part or lost spring tension, causing the part to sag

JANUARY 2012

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET

NOW OFFERING

1521


TOTAL SKUs

14 NEW SKUs!

749-637 [FL]
749-638 [FR]
A4 2008-02
S4 2004
Pop Code: D
VIO: 205,658



741-144 [FL]
741-145 [FR]
Eclipse 2005-00
Sebring 2005-01
Pop Code: C
VIO: 2,426,564



748-898 [RL]
748-899 [RR]
Pathfinder
2009-05
Pop Code: D
VIO: 229,413



Visit www.DormanProducts.com/GetMore
for Product Information, Installation Sheets, Product Videos and More!

Scan here to learn more ▶

