

OCTOBER 2011

Camshaft Phaser

Adjusts Camshaft timing for optimal engine performance



917-250
Ford 4.6, 5.4L,
4-Door
2011-05

Pop Code: C
VIO: 1,911,227

FAILURE MODE:

- Engine experiences loss of power accompanied by a knocking sound

License Plate Lens

Maintenance Item: Required to pass Inspection



STORE STOCK

68168
Avalanche, Escalade,
Sierra, Silverado,
Suburban, Tahoe,
Yukon
2010-01

Pop Code: A
VIO: 8,963,817

FAILURE MODE:

- Plastic housing breaks from collision

Heater Hose Assembly



RUST

626-304
Caravan, Town & Country
2008

Pop Code: C
VIO: 205,233



Coated to prevent corrosion

Fuel Door Hinges ALSO KNOWN AS FUEL TANK DOOR HINGE

Plastic hinges located on the Fuel Door that allow door to open and shut



924-140
Volvo S60 2009-01,
S80 2006-99, V70 2007-01,
XC70 2007-03, XC90 2009-03

Pop Code: C
VIO: 634,302

ALSO AVAILABLE!

924-141
Volvo 740, 940, 960
1998-83

Pop Code: D
VIO: 236,320

FAILURE MODE:

- Plastic becomes brittle over time and snaps during use

Door Hinge Assembly

Supports the operation of the door



924-116
Sprinter
2006-03
Back Cargo Doors

Pop Code: C
VIO: 235,212

FAILURE MODE:

- The metal bushing wears out over time from opening and closing the door causing the door to sag

Driveshaft Coupler

Connects Prop Shafts to Transmission, Transfer Case, or Differential Yokes

COMPLETE KIT

Includes All Hardware for a Complete Repair



935-403
BMW 3, 5, 6,
7, X5, Z3 Series
2011-76

Pop Code: D
VIO: 1,995,852



ALSO AVAILABLE!

935-101
3 Series 2006-92,
Corvette 2011-01

Pop Code: D
VIO: 967,591

FAILURE MODE:

- Rubber deteriorates over time due to wear and tear
- Results in increased vibration, clunking sound and, in severe cases, vehicle inoperability

BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

DORMAN®

NEW SINCE 1918

www.DormanProducts.com


FORMERLY "DEALER ONLY" PARTS

Now Available to the Aftermarket

OCTOBER 2011

Remanufactured Transfer Case Control Module

Plug & Play for Easy Installation (No Programming Required)



599-105
Avalanche, Escalade,
Sierra, Silverado,
Suburban, Tahoe, Yukon
2002-99

Pop Code: D
VIO: 3,489,251

FAILURE MODE:

- Corrosion, components degrade over time
- Will not shift in and out of 4WD

LINE EXTENSIONS

Plastic Backed Mirror Glass



50625
Aura 2009-07;
G6 2010-05;
Malibu 2008-04

Pop Code: D
VIO: 1,375,514

Vacuum Pump Pulley

Great Add-on Sale to Vacuum Pumps



300-700
E Series Van,
F-Series Pickup
2003-95


Pop Code: D
VIO: 1,145,120

FAILURE MODE:


- Damaged during removal and installation of Vacuum Pump

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET



748-546 [RL]
300, Charger, Magnum
2008-05
Pop Code: D
VIO: 1,014,097



749-552 [RL]
749-553 [RR]
Murano
2007-03
Pop Code: D
VIO: 306,692

NOW OFFERING
1500
TOTAL SKUs

21 NEW SKUs!

Visit www.DormanProducts.com/GetMore
for Product Information, Installation Sheets, Product Videos and More!

Scan here to learn more ▶



BE THE FIRST TO KNOW ABOUT FORMERLY "DEALER ONLY" PARTS!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492