

Fan Pulley Brackets



Replace the Piece, NOT the Assembly

Bracket is not available separately from the OE dealer, forcing you to buy unneeded components.



300-801
Toyota 3.0L 4Runner,
Pickup T100
1995-93



OE Brackets
Not Available at the
OE Dealer Separately

Now Available in the Aftermarket

- Support belt-driven fans on rear wheel drive vehicles with internally mounted water pumps
- Also known as a Water Pump Bracket
- Remember to check belt for cracking or glazing

COMMON REASONS FOR FAILURE

*Bearings Seize • Mounts Crack
Collision Repair*



Activant Path	Cooling System/ Radiator Cap, Fan Motor and Switch	Activant Code	DRF
----------------------	--	----------------------	-----

**Applications begin
on page 138.**

Fan Pulley Brackets



300-800

Toyota
1992-88 Toyota Pickups, 4-Runner
(6 cyl.).



300-801

Toyota
1995-93 Toyota Pickups, 4-Runner,
1994-93 T100 (all w/3.0L).



300-802

Toyota
2004-95 Toyota Truck, 4-Runner, T100,
Tacoma, Tundra.



300-803

Isuzu
1994-91 3.2L Isuzu Truck, Passport,
Rodeo, Trooper.



300-806

GM
1996-94 GM Sonoma, S10, Postal Service
Vans L4-2.2L.

Also Available From


Electronic Fan Clutch - pgs. 135-136
Power Steering Pulleys - pgs. 317-326
Smog Pump Pulleys - pgs. 469-472
Idler Pulleys - pg. 322

Fan Pulley Bracket Applications

Make/Model/ Engine	Year	Description	Dorman #
CHEVROLET TRUCK			
POSTAL SERVICE VAN			
L4 - 2.2L (134 CID)	1995-94	-	300-806
S10 PICKUP			
L4 - 2.2L (134 CID)	1996-94	-	300-806
GMC TRUCK			
S15 SONOMA			
L4 - 2.2L (134 CID)	1996-94	-	300-806
HONDA			
PASSPORT			
V6 - 3.2L (3165 cc)	1997-94	-	300-803
ISUZU			
RODEO			
V6 - 3.2L (3165 cc)	1997-94	-	300-803
TROOPER			
V6 - 3.2L (3165 cc)	1997-94	-	300-803


Make/Model/ Engine	Year	Description	Dorman #
TOYOTA TRUCK			
4 RUNNER			
V6 - 3.0L (2959 cc)	1992-88	-	300-800
V6 - 3.4L (3378 cc)	2002-96	-	300-802
PICKUP			
V6 - 3.0L (2959 cc)	1992-88	-	300-800
T100			
V6 - 3.0L (2959 cc)	1994-93	-	300-801
V6 - 3.4L (3378 cc)	1998-95	-	300-802
TACOMA			
V6 - 3.4L (3378 cc)	2000-95	-	300-802
TUNDRA			
V6 - 3.4L (3378 cc)	2004-00	-	300-802
V6 - 3.4L (3378 cc)	1999	From 2/99	300-802

Related Sales - Water Pump Stud Kits




23733 (4)

5/16"-24. Fits most GM water pumps.
Includes 4 studs, 4 nuts and 4 washers.



23737 (4)

M8-1.25. Fits S10 Blazer, Jimmy, Pickups,
1994-82. Includes 4 studs, 4 nuts, 4
washers.



23743 (4)

M6-1.0. Fits imports Honda, Nissan,
Toyota and others. Includes 4 studs, 4
nuts, 4 washers.