


# Transmission Shift Solenoid Pack

**Direct OE Replacement**



1 SKU  
Covers Over  
20 Different Models  
and 10 Million  
Registered  
Vehicles



## Easy to Diagnose

- Poor Shifting Quality
- Suddenly Locks into Second Gear (“Limp Home” mode)

## Easy to Replace - Externally Mounted

- Extremely Failure-Prone Chrysler Transmission Shift Solenoid Available at a Price That is Competitive with OE!
- Fits 2004-89 Chrysler Cars/Minivans with Overdrive (A604) Transmissions
- New **Hydraulic** Solenoid Technology — NOT Included in Most Traditional Transmission Solenoid Suppliers’ Programs

**Activant Path**

Auto Transmission/  
Transaxle/  
A/T Filters & Parts

**Activant Code**

DPD

Applications begin  
on page 534.

# Transmission Shift Solenoid



**698-100**

**Chrysler**  
2004-89 Chrysler vehicles w/ A604  
Transmission

Transmission Shift Solenoid

## Transmission Shift Solenoid Applications

Make/ Model/Year	Description	Dorman #
<b>CHRYSLER</b>		
<b>CIRRUS</b> 2000-95	-	<b>698-100</b>
<b>IMPERIAL</b> 1993-90	-	<b>698-100</b>
<b>LEBARON</b> 1995-89	-	<b>698-100</b>
<b>NEW YORKER</b> 1993-89	-	<b>698-100</b>
<b>PACIFICA</b> 2004	-	<b>698-100</b>
<b>PT CRUISER</b> 2003-01	-	<b>698-100</b>
<b>SEBRING</b> 2004-01	Exc. Coupe	<b>698-100</b>
2000-95	-	<b>698-100</b>
<b>TC MASERATI</b> 1991-89	-	<b>698-100</b>
<b>TOWN &amp; COUNTRY VAN</b> 2003-90	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>VOYAGER, GRAND VOYAGER</b> 2003-00	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>DODGE</b>		
<b>AVENGER</b> 2000-95	-	<b>698-100</b>
<b>CARAVAN, GRAND CARAVAN</b> 2003-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>DAYTONA</b> 1993-89	w/A604 4-Speed Auto Trans	<b>698-100</b>

Make/ Model/Year	Description	Dorman #
<b>DODGE (continued)</b>		
<b>DYNASTY</b> 1993-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>NEON</b> 2003-01	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>SHADOW</b> 1994-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>SPIRIT</b> 1995-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>STRATUS</b> 2004-01	Sedan	<b>698-100</b>
2000-95	-	<b>698-100</b>
<b>EAGLE</b>		
<b>TALON</b> 1998-95	w/A604 4-Speed Auto Trans, wo/Turbo	<b>698-100</b>
<b>PLYMOUTH</b>		
<b>ACCLAIM</b> 1995-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>BREEZE</b> 2000-96	-	<b>698-100</b>
<b>NEON</b> 2001	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>SUNDANCE</b> 1994-89	w/A604 4-Speed Auto Trans	<b>698-100</b>
<b>VOYAGER, GRAND VOYAGER</b> 2000-89	w/A604 4-Speed Auto Trans	<b>698-100</b>

### Transmission Shift Solenoid #698-100

**Symptom:** Poor Shift Quality. Car goes into "Limp Mode."

**Solution:** Dorman OE Solutions™ #698-100, just one SKU covers 2005-89 Chrysler Cars/Minivans with A604 transmission. That translates into coverage for over 20 different models and 10 million registered vehicles.

Dorman's **698-100** provides a solution that is easy to replace and externally mounted.